

Recall Detail	
Ref No	10000413
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	X series (E7x)
Dealer (phone no)	31936688
Subject	Replace the front drive shaft
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	A worn universal joint may lead to undesirable vibrations and to an increased noise level in the vehicle interior. In individual cases, the universal joint on the front drive shaft may break. The drive torque for the front axle can then no longer be transmitted.
Remedial Action	Replace the front drive shaft
Build Dates	04/2010-11/2010
Launch Date	11/02/2013
Tentative Date of Recall Completion	31/08/2013

1	L491013
2	L491027
3	L491067
4	L491073
5	L491108
6	L491111
7	L491121
8	L491126
9	L491134
10	L491146
11	L491147
12	L491167
13	L491269
14	L491272
15	L491273
16	L491284
17	LH67393
18	LJ88880
19	LL57150
20	LL57151
21	LL57152

22	LL57153
23	LL57154
24	LL57156
25	LL57158
26	LL57160
27	LL57162
28	LL57164
29	LL57165
30	LL57166
31	LL57167
32	LL57168
33	LL57170
34	LL57172
35	LL57173
36	LL57174
37	LL57175
38	LL57176
39	LL57177
40	LL57180
41	LL57181
42	LL57274

43	LL57277
44	LL57279
45	LL57324
46	LL57327
47	LL57329
48	LL57363
49	LL57371
50	LL57375
51	LL57377
52	LL57379
53	LL57385
54	LL57388
55	LL57393
56	LL57394
57	LL57537
58	LL57554
59	LL57560
60	LL57568
61	LL57574
62	LL57621
63	LL57624
64	LL57708
65	LL57757
66	LL57758
67	LL57759
68	LL57762
69	LL57764
70	LL57769
71	LL57770
72	LL57790
73	LL57799
74	LL57896
75	LL57897
76	LL57899
77	LL57901
78	LL57902
79	LL57903
80	LL57904
81	LL57907
82	LL57909

83	LL57922
84	LL57925
85	LL57927
86	LL57928
87	LL67029
88	LL67035
89	LL67036
90	LL67099
91	LL67103
92	LL67143
93	LL67164
94	LL67165
95	LL67166
96	LL67167
97	LL67183
98	LL67187
99	LL67207
100	LL67210
101	LL67218
102	LL67219
103	LL67223
104	LL67244
105	LL67245
106	LL67258
107	LL67261
108	LL67291
109	LL67292
110	LL67328
111	LL67402
112	LL79289
113	LL79308
114	LL79341
115	LL79342
116	LL79349
117	LL79350
118	LL79361
119	LL79381
120	LL79385
121	LL79394
122	LL80013

123	LL80020
124	LL80021
125	LL80024
126	LL80025
127	LL80026
128	LL80027
129	LL80028
130	LL80044
131	LL80047
132	LL80048
133	LL80053
134	LL80055
135	LL80057
136	LL80058
137	LL80065
138	LL80066
139	LL80068
140	LL80085
141	LL80090
142	LL80091
143	LL80104
144	LL80118
145	LL80121
146	LL80131
147	LL80135
148	LL80141
149	LL80146
150	LL80157
151	LL80160
152	LL80161
153	LL80163
154	LL80166
155	LL80167
156	LL80168
157	LL80169
158	LL80170
159	LL80171
160	LL80172
161	LL80178
162	LL80181

163	LL80182
164	LL80187
165	LL80194
166	LL80204
167	LL80214
168	LL80215
169	LL80216
170	LL80217
171	LL80220
172	LL80221
173	LL80229
174	LL80235
175	LL80236
176	LL80265
177	LL80266
178	LL80269
179	LL80270
180	LL80271
181	LL80283
182	LL80291
183	LL80297
184	LL80298
185	LL80299
186	LL80321
187	LL80322
188	LL80326
189	LL80344
190	LL80345
191	LL80350
192	LL80351
193	LL80352
194	LL80365
195	LL80366
196	LL80367
197	LL80368
198	LL80369
199	LL80371
200	LL80372
201	LL80373
202	LL80374

203	LL80375
204	LL80376
205	LL80378
206	LL80379
207	LL80385
208	LL80393
209	LL80394
210	LL80396
211	LL80398
212	LL80400
213	LL80413
214	LL80416
215	LL80418
216	LL80419
217	LL80420
218	LL80422
219	LL80423
220	LL80426
221	LL80427
222	LL80428
223	LL80429
224	LL80430
225	LL80431
226	LL80432
227	LL80433
228	LL80435
229	LL80440
230	LL80442
231	LL80443
232	LL80452
233	LL80453
234	LL80454
235	LL80458
236	LL80459
237	LL80462
238	LL80463
239	LL80464
240	LL80465
241	LL80466
242	LL80469

243	LL80473
244	LL80476
245	LL80479
246	LL80480
247	LL80484
248	LL80485
249	LL80488
250	LL80491
251	LL80494
252	LL80495
253	LL80496
254	LL80506
255	LL80516
256	LL80519
257	LL80520
258	LL80521
259	LL80522
260	LL80527
261	LL80529
262	LL80530
263	LL80584
264	LL80597
265	LL80640