

Transport Department Notice

Temporary Traffic and Transport Arrangements on Fanling Highway

Notice is hereby given that to facilitate road works, the following temporary traffic and transport arrangements will be implemented on Fanling Highway from 01.00 a.m. to 05.30 a.m. on 10 April 2025:

(1) ROAD CLOSURE

The following road sections will be temporarily closed to all vehicular traffic:

- i. The slip road leading from Jockey Club Road southbound to Fanling Highway southbound; and
- ii. The slip road leading from Pak Wo Road northbound to Fanling Highway southbound.

(2) TRAFFIC DIVERSION

- i. Vehicles on Jockey Club Road southbound near Tong Hang heading for Heung Yuen Wai Boundary Control Point will be diverted via Pak Wo Road southbound, slip road, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Fanling Highway northbound and Heung Yuen Wai Highway northbound;
- ii. Vehicles on Jockey Club Road southbound near Tong Hang heading for Tai Po and Kowloon will be diverted via Pak Wo Road southbound, slip road, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound;
- iii. Vehicles on Pak Wo Road northbound near Dawning Views heading for Heung Yuen Wai Boundary Control Point will be diverted via Pak Wo Road northbound, Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Sha Tau Kok Road northbound, roundabout and Heung Yuen Wai Highway northbound; and
- iv. Vehicles on Pak Wo Road northbound near Dawning Views heading for Tai Po and Kowloon will be diverted via Pak Wo Road northbound, Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, slip road, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound.

(3) PUBLIC TRANSPORT SERVICES ARRANGEMENTS

(A) Franchised Bus Services

KMB Route Nos. 277X (Lam Tin Station bound), 278X (Tsuen Wan bound) and W3 (West Kowloon Station Bus Terminus bound) will be diverted via Wah Ming Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound, Lam Kam Road Interchange and Tolo Highway southbound before resuming their original routeings. Their en-route stops at Fanling Highway Bus-bus interchange will be suspended.

(B) Green Minibus Service

GMB Route No.501S (Kwun Tong bound) will be diverted via Pak Wo Road northbound, Jockey Club Road northbound, Sha Tau Kok Road – Lung Yeuk Tau roundabout, Jockey Club Road southbound, Pak Wo Road southbound, Wah Ming Road southbound, Wo Hing Road eastbound, Tai Wo Service Road West southbound and Tai Po Road - Tai Wo southbound before resuming its original routeing.

Appropriate traffic signs will be erected on site to guide motorists. Motorists are advised to follow the instructions on site and drive in utmost care. The public transport operators will display notices to advise passengers of the above temporary arrangements.

LEE Chung-yan, Angela *Commissioner for Transport*