

Recall Detail

Ref No	10000560
Manufacturer	TESLA
Vehicle Class	Private Car
Model/Type	Model S / Saloon
Dealer (phone no)	3974-0251
Subject	Voluntary recall for Seatbelt inspection
Progress	Running
Affected Vehicle Identification Number (VIN)	All Model S in Hong Kong registered before 19/11/2015.
Description of Defect, how it came to light, and possible consequences if ignored.	Front seat belt that was not properly connected to the outboard lap pretensioner. In the event of a crash, a seatbelt in this condition would not provide full protection.
Remedial Action	We have decided to conduct a voluntary recall as a proactive and precautionary measure to inspect all front Model S seat belts
Build Dates	2014-15
Launch Date	21/11/2015
Tentative Date of Recall Completion	31/12/2015