

## Recall Detail

<b>Ref No</b>	<b>10000738</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	E-Class / 213
<b>Dealer (phone no)</b>	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Replace left seat belt in rear (9290050)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The propellant mixing ratio of certain seat belt tensioner squibs in affected vehicles may not meet the specifications.  In an accident with activation of the left seat belt tensioner in the rear, this may not deploy.  As a result, the restraint effect of this seat belt tensioner would not be ensured. This may increase the risk of injury to the occupants.
<b>Remedial Action</b>	Replace the potentially affected seat belt in affected vehicles as a precautionary measure
<b>Build Dates</b>	05/08/2016 - 28/10/2016
<b>Launch Date</b>	15/11/2017
<b>Tentative Date of Recall Completion</b>	30/04/2018

1	WDD2130422A095263
2	WDD2130422A095330
3	WDD2130422A095458

4	WDD2130422A095687
5	WDD2130422A095919
6	WDD2130422A096007

7	WDD2130422A096018
8	WDD2130422A096155
9	WDD2130422A096352
10	WDD2130422A096388
11	WDD2130422A096456
12	WDD2130422A096484
13	WDD2130422A096559
14	WDD2130422A096768
15	WDD2130422A096847
16	WDD2130422A096904
17	WDD2130422A096962
18	WDD2130422A096995
19	WDD2130422A097137
20	WDD2130422A097275
21	WDD2130422A097287
22	WDD2130422A097514
23	WDD2130422A097687
24	WDD2130422A097931
25	WDD2130422A098146
26	WDD2130422A098240
27	WDD2130422A098393
28	WDD2130422A098492
29	WDD2130422A098692
30	WDD2130422A098900
31	WDD2130422A098991
32	WDD2130422A099060
33	WDD2130422A099181
34	WDD2130422A099308
35	WDD2130422A099447
36	WDD2130422A099668
37	WDD2130422A099670
38	WDD2130422A099727
39	WDD2130422A099801
40	WDD2130422A099916
41	WDD2130422A100050
42	WDD2130422A100277
43	WDD2130422A100339
44	WDD2130422A130883
45	WDD2130482A131420
46	WDD2130482A131507

47	WDD2132422A135401
48	WDD2132422A135923
49	WDD2132422A139983