

Recall Detail

Ref No	10001055
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	S-Class/ 223
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Bolting of Airbag Control Unit (5494205)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	The airbag control unit might not have been bolted according to specifications. In this case, the airbag control unit might detect incorrect acceleration values while driving. As a result, an unintended deployment of the restraint systems cannot be ruled out completely. Furthermore, in case of a crash, the restraint systems might not be activated as specified. Depending on the scenario, the risk of a crash or injury would be increased.
Remedial Action	As a precautionary measure, to check the airbag control unit threaded connection in the affected vehicles and correct it if necessary.
Build Dates	17/11/2020 – 24/02/2021
Launch Date	29/03/2022
Tentative Date of Recall Completion	31/12/2022

1	W1K2231612A011596
2	W1K2231612A013844
3	W1K2231612A016528
4	W1K2231612A019771

5	W1K2231612A023199
6	W1K2231612A024651
7	W1K2231612A024891
8	W1K2231612A025445

9	W1K2231612A025749
10	W1K2231612A026043
11	W1K2231612A026967
12	W1K2231612A027400
13	W1K2231612A027517
14	W1K2231612A027534
15	W1K2231612A029997
16	W1K2231612A030236
17	W1K2231632A023257
18	W1K2231632A023625
19	W1K2231632A028896
20	W1K2231632A028968
21	W1K2231632A028985
22	W1K2231632A029838
23	W1K2231632A030097
24	W1K2231632A030738
25	W1K2231632A031848