

Recall Detail	
Ref No	10001098
Manufacturer	TESLA
Vehicle Class	Private Car
Model/Type	Model S
Dealer (phone no)	Tesla Motors HK Ltd. (3974 0251)
Subject	Update Vehicle Firmware for Electronic Power Steering Assist (EPAS) Calibration
Progress	Running
Affected Vehicle Identification Number (VIN)	Listed as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Release of Software Package (2022.36) changed calibration values for the electronic power assist steering (EPAS) system, which may incorrectly classify forces from adverse road conditions (i.e., potholes or bumps) as unexpected steering assist torque, possibly resulting in reduced or lost power steering assist.</p> <p>Reduced or lost power steering assist does not affect steering control, but could make steering more difficult for the driver, particularly at low speeds.</p>
Remedial Action	Update the Firmware
Build Dates	2017 - 2020
Launch Date	07 November 2022
Tentative Date of Recall Completion	1 January 2023

1	5YJSB7E20LF403746
2	5YJSB7E21KF337545
3	5YJSB7E21LF354928
4	5YJSB7E23JF265374
5	5YJSB7E24LF403538
6	5YJSB7E26JF267880
7	5YJSB7E26MF419564
8	5YJSB7E28JF257626
9	5YJSB7E29JF269395
10	5YJSB7E2XJF282379
11	5YJSB7E47KF311002
12	
13	
14	
15	

16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	