

Recall Detail	
Ref No	10000398
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Passenger Car
Model/Type	i-MiEV (HA3W)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Fail safe mode change in CMU
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Since the fail-safe mode detection on the traction battery system is too aggressive, the system may detect as a failure of traction battery system and the system may turn into fail-safe mode. As MMC modified the program to mitigate the judgment of fail-safe mode detection, the traction battery system program is to be updated on all of affected vehicles.
Remedial Action	Rewrite the CMU program.
Build Dates	2010-2012
Launch Date	04/09/2012
Tentative Date of Recall Completion	03/09/2013

1	HA3W 0001130
2	HA3W 0001133
3	HA3W 0001135
4	HA3W 0001555
5	HA3W 0001560
6	HA3W 0001604
7	HA3W 0001605
8	HA3W 0001607
9	HA3W 0001608
10	HA3W 0001609
11	HA3W 0001614
12	HA3W 0001616
13	HA3W 0001617
14	HA3W 0001613
15	HA3W 0001618
16	HA3W 0001620
17	HA3W 0001673
18	HA3W 0001674
19	HA3W 0001679

20	HA3W 0001680
21	HA3W 0001681
22	HA3W 0001682
23	HA3W 0001685
24	HA3W 0001687
25	HA3W 0001692
26	HA3W 0001695
27	HA3W 0001700
28	HA3W 0001703
29	HA3W 0001706
30	HA3W 0001708
31	HA3W 0001710
32	HA3W 0001697
33	HA3W 0001712
34	HA3W 0001716
35	HA3W 0001793
36	HA3W 0001796
37	HA3W 0001799
38	HA3W 0002516

39	HA3W 0002909
40	HA3W 0003213
41	HA3W 0003238
42	HA3W 0003267
43	HA3W 0003289
44	HA3W 0003326
45	HA3W 0003695
46	HA3W 0003697
47	HA3W 0003699
48	HA3W 0003702
49	HA3W 0003704
50	HA3W 0003711
51	HA3W 0003713
52	HA3W 0003717
53	HA3W 0003720
54	HA3W 0003721
55	JMALDHA3WBU000356
56	JMALDHA3WBU000360
57	JMALDHA3WBU000361
58	JMALDHA3WCU000203
59	JMALDHA3WCU000205
60	JMALDHA3WCU000208
61	JMALDHA3WCU000210
62	JMALDHA3WCU000212
63	JMALDHA3WCU000201
64	JMALDHA3WCU000217
65	JMALDHA3WCU000218
66	JMALDHA3WCU000219