

## Recall Detail

<b>Ref No</b>	<b>10001172</b>
<b>Manufacturer</b>	Mitsubishi Fuso Truck & Bus Corporation
<b>Vehicle Class</b>	Bus
<b>Model/Type</b>	Fuso ROSA BE7
<b>Dealer (phone no)</b>	Universal Cars Limited (Tel: 39138800 Customer Service Hotline)
<b>Subject</b>	Stop Lamp Switch Incorrect Installation
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to the stop lamp switch set in an inappropriate position, when apply light braking EZGO may not operation.
<b>Remedial Action</b>	Adjust stop lamp switch clearance.
<b>Build Dates</b>	From 16/02/2022 to 18/09/2022
<b>Launch Date</b>	13/05/2024
<b>Tentative Date of Recall Completion</b>	06/05/2027

1	BE741EM10001
2	BE741GM10019
3	BE741GM10020
4	BE741GM10021
5	BE741GM10022
6	BE741GM10023
7	BE741GM10024
8	BE741GM10025
9	BE741GM10026
10	BE741GM10027
11	BE741GM10028
12	BE741GM10029

13	BE741GM10030
14	BE741GM10031
15	BE741GM10032
16	BE741GM10033
17	BE741GM10034
18	BE741GM10035
19	BE741GM10036
20	BE741GM10037
21	BE741GM10038
22	BE741GM10039
23	BE741GM10040
24	BE741GM10041

25	BE741GM10042
26	BE741GM10043
27	BE741GM10044
28	BE741GM10045
29	BE741GM10046
30	BE741GM10047
31	BE741GM10048
32	BE741GM10049
33	BE741GM10050
34	BE741GM10051
35	BE741GM10052
36	BE741GM10053
37	BE741GM10054
38	BE741GM10055
39	BE741GM10056
40	BE741GM10057
41	BE741GM10058
42	BE741GM10059
43	BE741GM10060
44	BE741GM10061
45	BE741GM10062
46	BE741GM10063
47	BE741GM10064
48	BE741GM10065

49	BE741GM10066
50	BE741GM10067
51	BE741GM10068
52	BE741GM10069
53	BE741GM10071
54	BE741GM10073
55	BE741GM10074
56	BE741GM10077
57	BE741GM10079
58	BE741GM10080
59	BE741GM10081
60	BE741GM10082
61	BE741GM10083
62	BE741GM10084
63	BE741GM10085
64	BE741GM10086
65	BE741GM10088
66	BE741GM10089
67	BE741GM10090
68	BE741GM10091
69	BE741GM10092
70	BE741GM10093
71	BE741GM10094
72	BE741GM10105

73	BE741GM10106
74	BE741GM10107
75	BE741GM10108
76	BE741GM10109
77	BE741GM10110
78	BE741GM10111
79	BE741GM10112
80	BE741GM10113
81	BE741GM10114
82	BE741GM10115
83	BE741GM10116
84	BE741GM10117
85	BE741GM10118
86	BE741JM10331
87	BE741JM10352
88	BE741JM10356
89	BE741JM10431
90	BE741JM10433
91	BE741JM10434
92	BE741JM10435
93	BE741JM10438
94	BE741JM10443
95	BE741JM10448
96	BE741JM10461

97	BE741JM10462
98	BE741JM10463
99	BE741JM10464
100	BE741JM10465
101	BE741JM10466
102	BE741JM10467
103	BE741JM10468
104	BE741JM10469
105	BE741JM10470
106	BE741JM10471
107	BE741JM10472
108	BE741JM10473
109	BE741JM10474
110	BE741JM10475
111	BE741JM10476
112	BE741JM10477
113	BE741JM10478
114	BE741JM10479
115	BE741JM10480
116	BE741JM10481
117	BE741JM10482
118	BE741JM10483
119	BE741JM10484
120	BE741JM10485

121	BE741JM10486
122	BE741JM10487
123	BE741JM10488
124	BE741JM10489
125	BE741JM10490
126	BE741JM10491
127	BE741JM10492
128	BE741JM10493
129	BE741JM10494
130	BE741JM10495
131	BE741JM10496
132	BE741JM10497
133	BE741JM10498
134	BE741JM10499
135	BE741JM10500
136	BE741JM10501
137	BE741JM10502
138	BE741JM10503
139	BE741JM10504
140	BE741JM10505
141	BE741JM10506
142	BE741JM10508
143	BE741JM10510
144	BE741JM10511

145	BE741JM10513
146	BE741JM10517
147	BE741JM10518
148	BE741JM10520
149	BE741JM10524
150	BE741JM10525
151	BE741JM10526
152	BE741JM10528
153	BE741JM10529
154	BE741JM10530
155	BE741JM10547
156	BE741JM10550